

Project No.	Client	Location	Boring No.	Monitoring Well No.	Date
00445	Beacon Bay Auto Wash	481 E. 17 th St., Costa Mesa	CB2		August 3, 2005
PID	BLOWS/ft. Sampler	DEPTH in feet	USCS Designation & Soil Type	Color	Secondary Characteristics
0	9-11-12	5	Silty Clay (CL)	Olive Brown	Stiff, Sl Moist, No Odor
0	7-16-20	10	Silty Sands (SM)	Tan to Brown	M. Dense, Dry, No Odor
10	12-15-22	15	Clayey Silt (CL)	Light Grey	Very Stiff, Moist, Sl Odor
20	9-18-26	20	Silty Sands (SM)	Grey	M. Dense, Wet, Sl Odor
5	11-23-31	25			Sl Odor
0	11-13-25	30		Tan to Grey	M. Dense, Wet, No Odor
0	10-10-15	35	Silty Clay (CL)	Light Grey	Stiff, Wet No Odor
Field Engineer	Drilling Contractor	Drilling Foreman	Boring terminated at 35'. Groundwater encountered at 16-17'. Boring backfilled with soil from boring. Overflow soil drummed and manifested.		
M. Anselmo	J & H - Hollow Stem	Conrad			